



GOVERNMENT OF THE DISTRICT OF COLUMBIA
CONSTRUCTION CODES COORDINATING BOARD
c/o DCRA – 1100 4th Street, SW, Washington, DC 20024

CODE CHANGE PROPOSAL FORM

PAGE: 1 of 2

CODE: Building SECTION NO.: 3009.1 SUBCOMMITTEE AMENDMENT NO.: BC-Ev-30-10-13

PROPOSING SUBCOMMITTEE: Elevator CHAIR: Khokhar PHONE: 202 481 3386 E-mail: jatinder.khokhar@dc.gov

DATES OF PROPOSAL: 04/23/12 CCCB PRESENTATION: 5/3/12 CCCB APPROVAL: 6.8.12

06.01.12 – Revised by TAG

CHECK ONE x *Revise section to read as follows:* *Delete section and substitute the following:*
Add new section to read as follows: *Delete section without substitution.*

TYPE ALL TEXT IN 12-POINT TIMES NEW ROMAN FONT
~~LINE THROUGH TEXT TO BE DELETED~~ (highlight text, under Format, click font and check strikethrough)
UNDERLINE TEXT TO BE ADDED
Use additional sheets of the form, if necessary.

See Attached Page

Anticipated impact of code change on cost of construction (CHECK ONE)
 Increase Decrease Negligible Unknown
Per 1,000 SF single-family dwelling to
Per 1,000SF of commercial building to

JUSTIFICATION OF CHANGE:
Please reference one or more of the criteria required
X To address a critical life/safety, health, general welfare need.
To address a specific District of Columbia policy or statute
 For consistency with federal, or with reference to the Metro DC area (MD, VA) codes
 Address a unique character issue in the District of Columbia
 Correction of errors and omissions
 Other (explain)



This is an administrative change requiring MCP's to be kept on site and be accessible for reference to assure the proper inspections and tests of the equipment are conducted.

Insert the following language in Section 3009.1 in the Building Code to read as follows:

3009 AMENDMENTS TO STANDARD ASME A17.1

3009.1 ASME A17.1

Strike Section 8.6.1.2.1(d) of ASME A17.1 and insert new Section 8.6.1.2.1(d) to ASME A17.1 in its place to read as follows:

Section 8.6.1.2. GENERAL MAINTENANCE REQUIREMENTS

8.6.1.2.1(d) The Maintenance Control Program shall be accessible to the elevator personnel and shall document compliance with 8.6. The Maintenance Control Program (MCP) shall be located on site, either in printed or digital media form. Access to the MCP shall be provided on site for review/viewing and reference for inspectors and elevator personnel to properly perform their respective duties during inspection and testing of the equipment. A MCP shall be provided for each different type of equipment installed.